

Our Ref: P18.172-MRWA\_OCCUPANT NOTIFICATION

**RE: NOTIFICATION OF UNRESTRICTED ASBESTOS REMOVAL WORKS**

Thuroona Services Pty Ltd (Unrestricted asbestos licence holder # WA 184) has been engaged by Main Roads Western Australia . Thuroona intends to carry out friable asbestos removal works at the location listed below. It is a requirement of Worksafe that the occupant and adjoining properties are made aware that friable removal works are being undertaken.

**SITE ADDRESS:** Roebourne – Wittenoom Rd Wittenoom Western Australia (Between SLK 25.89 – SLK 75.05)

**SITE DESCRIPTION:** Public Road Reserve

**LOCATION:** Approx 10m inwards from side of road and within roadway

**TYPE OF ASBESTOS:** Raw Crocidolite asbestos (Previously in Hessian Bags which have been degraded)

**START DATE:** 14/11/2018

**FINISH DATE:** 04/12/2018

**WORKING TIMES:** 0700hrs – 1700hrs


**SUPERVISORS NAME:** Mr Samuel Jackson **CONTACT NUMBER:** 0413 253 558 or 1300 848 766 (24hr)

The following safe working procedures will apply:

- Asbestos signage, barriers and traffic calming devices(Road Works signs/high visibility bollards)
- Works will temporarily cease while vehicles are approaching the works area, the external supervisor will be in contact via two-way radio to advise of oncoming vehicles.
- PVA particle binder, surfactant and water will be applied to area to mitigate dust release.
- Operatives removing asbestos are required to undergo decontamination on leaving work areas. A mobile 5 stage trailer mounted decontamination unit will be placed directly next to the works area.
- Operatives will adopt personal protective equipment and utilise respiratory protective equipment when removing / remediating asbestos.
- Asbestos removal will be supervised by highly qualified asbestos supervisors and all operatives are trained and proficient in safe asbestos removal techniques relating to friable asbestos removal
- Asbestos containing materials will be bagged on-site, placed in steel drums and disposed of at a Department of Environment approved asbestos landfill site.
- GHD Pty Ltd will conduct a thorough visual inspection of the Asbestos Work Area / Work Site during and at the completion of the works, following their satisfactory inspection they will issue the site with a Clearance Certificate.
- Air Monitoring will be undertaken on site during the removal process and on completion of works

If there is any further information required, please contact me directly on the number listed below

Regards,



Samuel Jackson

Samuel@thuroonaservices.com.au